Known bug report for QubeCL and QubeDL

ppqSense App.Note no. 3

ppqSense s.r.l

ppqSense Development Team

Revision 1.0, 2025.06.06





In this document, the known bug affecting the QubeCL and QubeDL drivers are reported, along with a small description and the firmware and/or control software releases affected by each bug.

Contents

1 Current spikes to maximum value when very low setpoints are used 2

Revision 1.0 Pag. 1 - 3



1 Current spikes to maximum value when very low setpoints are used

SEVERITY: HIGH

TYPE: FIRMWARE (version V16.0 or lower)

DESCRIPTION: By setting some specific current values, always lower than 5 mA, the maximum current is delivered without respecting the set limit of IMAX.

SOLUTION: for firmware versions higher than 16.0, a protection has been added that, based on the current reading, places the Qube in a safe state in case the readed current should spike above the IMAX limit.

From version 17.4.9, the bug has been eliminated.

For older firmware versions it is possible to contact ppqSense staff in order to update the firmware to a compatible, bug-fixed version.

Revision 1.0 Pag. 2 - 3



Revision History

| Revision | Date | Author(s) | Description |
|----------|------------|-----------|------------------|
| 1.0 | 2025.06.06 | LM | First redaction. |

Revision 1.0 Pag. 3 - 3